


SECTION A-A



SECTION B-B


NOTES ON PLANS:

FOAM JOINT SEAL TO BE CUT, HEAT WELDED AND TURNED UP PARALLEL TO SLOPED FACE OF THE BARRIER RAIL.


THE JOINT SHALL BE SAWED PRIOR TO THE CASTING OF THE BARRIER RAIL.

FOAM JOINT SEAL DETAILS  
@ END BENT FOR BARRIER RAIL

**FIGURE 12 - 10**



### SECTION A-A



### SECTION B-B

#### NOTES ON PLANS:

FOAM JOINT SEAL TO BE CUT, HEAT WELDED AND TURNED UP PARALLEL TO SLOPED FACE OF THE BARRIER RAIL.

THE JOINT SHALL BE SAWED PRIOR TO THE CASTING OF THE BARRIER RAIL.

FOAM JOINT SEAL DETAILS  
@ END BENT FOR BARRIER RAIL

**FIGURE 12 - 10 M**